

## EPA Region 10 Photolog

Clean Air Act (CAA) Partial Compliance Evaluation (PCE)

Columbia Pacific Biorefinery – Clatskanie, OR

Dates: September 25, 2015

All photographs depicted in this photolog were taken September 25, 2015 at the times indicated below by Zach Hedgpeth or Sandra Brozusky of EPA Region 10 using a Panasonic DMC-TZ5 digital camera. Times indicated are Pacific Daylight Time.

Photos may have been resized, rotated, annotated, and cropped for use in this photolog.

Photo P1010052.jpg

9/25/15 – 11:14

Description:

Aerial photo of facility.



Photo P1010053.jpg

9/25/15 – 11:22

Description:

Rail unloading area.



Photo P1010054.jpg

9/25/15 – 11:23

Description:  
Rail unloading area.



Photo P1010055.jpg

9/25/15 – 12:02

Description:  
Two 100,000 barrel storage tanks.



Photo P1010056.jpg

9/25/15 – 12:04

Description:

Two 100,000 barrel storage tanks.



Photo P1010057.jpg

9/25/15 – 12:47

Description:

View of marine loading facility from dock entrance road.





Photo P1010058.jpg

9/25/15 – 12:49

Description:  
Marine vapor control burners.



Photo P1010059.jpg

9/25/15 – 13:04

Description:  
Barge at dock.



Photo P1010060.jpg

9/25/15 – 13:04

Description:  
Barge at dock.



Photo P1010061.jpg

9/25/15 – 13:08

Description:  
View of vapor control unit from dock.



Photo P1010062.jpg

9/25/15 – 13:08

Description:  
View of vapor control unit from dock  
(close-up).





Photo P1010063.jpg

9/25/15 – 13:10

Description:  
Vapor collection hose on barge  
(yellow hose).



Photo P1010064.jpg

9/25/15 – 13:33

Description:  
View of vapor control unit from dock.

